

BETHANY SPECIAL UTILITY DISTRICT

**133 S. CR 810
ALVARADO, TX. 76009
OFFICE: 817-790-2516
FAX: 817-790-2525**

November 28, 2016

Dear Customer

The Bethany Special Utility District water system PWS #1260016 has violated the monitoring and reporting requirements set by Texas Commission on Environmental Quality (TCEQ) in Title 20, Texas Administrative Code (.30 TAC) Section 290, Subchapter F. Even though these were not emergencies, as our customer, you have the right to know what happened and what we did to correct this situation.

We are required to monitor your drinking water for specific contaminants on a regular basis. Results of regular monitoring are an indicator of whether or not our drinking water meets health standards. During July 2016 monitoring period we did not complete all the monitoring paperwork. ***The violation was done by using a unknown address to TCEQ as a monitoring point in the system. Bethany SUD did not notify TCEQ on the change in the monitoring point.***

Be assured that samples and results taken within the water system were found to be in compliance with all State and Federal Regulations. This report was timely conducted, but one of the sampling sites was not on TCEQ monitoring report.

Contaminant Sampling was for copper and lead requirements. The sampling is taken periodically. The 20 samples will be taken again in July 2017.

Bethany SUD is working with TCEQ to update our 20 testing sites as well as 20 back-up sites so this will not be an issue again.

This notice is being sent to you by Bethany SUD PWS #1260016, Alvarado, TX.

Sincerely
Bethany Special Utility District